

Memo. No. SE/RE/G/6057—3—/87 (Technical Branch) dated 29—8—1987.

Sub: Avoidance of accidents due to paralleling of captive generator (installed by consumers) with Board supply or back feeding to Board's lines—Preventive measures—Orders issued.

In order to avoid occurrence of accidents due to paralleling of captive generator (installed by the consumer) supply with Board supply or due to back feeding of generator supply into Boards lines and equipments, field officers are requested to instruct the staff and workers to adopt the following safety precautions.

- (i) The field workers should avail self line clear before attending any work on lines and equipments whenever they attend works independently.
 - (ii) Earthing of lines/equipments should be done on both sides of the work spot.
2. Field Officers should ensure that adequate earthrods are supplied to the workers.
 3. Field staff and workers should also be instructed to identify the areas where captive generators are in operation and take extra precautionary measures before taking up works in such areas.

D. S. Nelson,
Member (Distribution)